

North Level District I.D.B. PSCA Works



07/08/2014

Work completed under the agreement in 2014/15.

Tidal River Nene Cradge Bank Repair Work, June – August 2014

Tidal River Nene Dredging Work, August – November 2014

Fluvial River Nene Cradge Bank Repair Work, August 2014

Tidal River Welland Dredging Work, January – February 2015

Mitigation Works, Whittlesey Washes Project – February – March 2014



Tidal Nene Cradge Bank repair works



05/14/2014

Tidal Nene Cradge Bank repair works

Surveying the damage



05/14/2014

Tidal Nene Cradge Bank repair works

Hitachi ZX210 placing the material on the south face of the bank



Tidal Nene Cradge Bank repair works

Typical dig when re-profiling



06/06/2014

Tidal Nene Cradge Bank repair works

Re-profiled river bank



07/02/2014

Tidal Nene Cradge Bank repair works

Excavated material used for bank repair's



06/06/2014

Tidal Nene Cradge Bank repair works

Levelling material



Tidal Nene Cradge Bank repair works

Final trim of material



Tidal River Nene Dredging Works



Tidal River Nene Dredging Works



Tidal River Nene Dredging Works

Levelling 2013 dredging's



Fluvial Nene Cradge Bank Repair's



Fluvial Nene Cradge Bank Repair's

Typical damage



Tidal Welland Dredging



Mitigation Work – Whittlesey Washes Project



Looking forward to 2015/16 work.....

Mitigation Works, Whittlesey Washes Project – Completed February 2015

Tidal River Nene Cradge Bank Repair Work, June – August 2015

Tidal River Nene Dredging Work, August – November 2015

Fluvial River Nene Cradge Bank Repair Work, August 2015

Tidal River Welland Dredging Work, January – February 2016

Gravel Dyke Weir Restoration



North Level District I.D.B.
www.northlevelidb.org
Follow us on Twitter @Northlevelidb

Partnership?



Follow the progress of our work via;



@Northlevelidb



Fenland Drainage Group



North Level District I.D.B.
www.northlevelidb.org
Follow us on Twitter @Northlevelidb